

General Environmental Incident Summary

Incident: 4153 **Date/Time Notice:** 6/29/2016 **DEM Incident No:**
Responsible Party: Sterling Construction Management, LLC
Date Incident: 6/29/2016 **Time Incident:** **Duration:**
County: Dunn **Twp:** 148 **Rng:** 97 **Sec:** 20 **Qtr:**
Lat: 47.63105 **Long:** -103.07700 **Method:** Navigation quality GPS
Location Description: Bear Creek NGL Pipeline Spread 2 Station # 1350+50 (Killdeer, ND nearest town)

Submitted By: Chase Edmiston **Affiliation:**
Address: 100 West Fifth Street
City: Tulsa **State:** OK **Zip:** 74103

Received By:

Contact Person:

10020 HWY 200 East
Dunn Center, ND

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Diesel fuel

Volume Spilled: 1.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Leak from diesel refueling tank

Risk Evaluation:

Minimal impact

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Localized area of soil was impacted. Spill occurred in upland area and no surface water or other environmentally sensitive areas were affected

Action Taken or Planned:

Spill was immediately identified, contained using spill kit, and affected soil transported to approved disposal facility.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/29/2016 ***Status:*** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up is necessary and will be completed on a quarterly basis.